

Tree removal impact survey - Dixons Bank

Ref	Type	Height (m)	Water Demand	Distance of influence	Distance From (Closest) Property (m)	Condition
1	Swedish White Maple	8	M	7	22	OK
2	Norway Maple	8	M	7	29	OK
3	Norway Maple	8	M	7	26	OK
4	Swedish Whitebeam	5	M	7	23	OK
5	Whitebeam	6	M	7	24	OK
6	Swedish Whitebeam	7	M	7	24	OK
7	Whitebeam	7	M	7	23	OK
8	Norway Maple	9	M	8	21	OK
9	Norway Maple	9	M	8	20	OK
10	Whitebeam	7	M	7	23	OK
11	Swedish Whitebeam	7	M	7	30	OK
12	Whitebeam	7	M	7	25	OK
13	Ash	8	M	7	23	OK
14	Apple	4	M	7	18	OK
15	Norway Maple	8	M	7	20	OK
16	Swedish Whitebeam	7	M	7	28	OK
17	Ash	11	M	10	24	OK
18	Norway Maple	6	M	7	25	OK
19	Whitebeam	6	M	7	26	OK
20	Birch	8	L	5	25	OK
21	Whitebeam	6	M	7	27	OK
22	Missing (assumed ASH)	11	M	10	27	OK
23	Whitebeam	5	M	7	26	OK
24	London Plane	8	M	7	27	OK
25	Hawthorn	6	H	7	24	OK